



REPAIR & MITIGATION

# HRH Bypass Cracking

Diederic Godin, P.Eng. (AB) – Capital Power: Senior Manager, Mechanical & Optimization

Ory Selzer – IMI CCI: Valve Doctor, Manager – Application Engineering

Support from: Adrian Martinez, P.Eng. – Plant Engineer, Goreway Power Station



### Goreway Power Station

- Brampton, ONT, CAN (Toronto)
- Commercial June 2009
- 875MW 3-on-1
- GE 7FB\*.04 Gas Turbines
- SST-5000 Steam Turbine
- EPC SNC Lavalin
- Purchased by Capital Power in 2019







### HRH Bypass — Application Overview



- Bypass HRH steam to condenser during startup, shutdown & trips
- Largest Bypass Valves
  - 16 20" Inlet
  - 24 42" Outlet
- Highest temperature differences
  - STEAM = ~1050F
  - WATER = ~120F>900F Difference!
- Largest spray30% Water to Steam







### Initial Failures

- Liners removed several years into operation due to cracks
- Cracks at nozzle housing to pipe connections [point A]
- Water manifold cracks
   [point B]
- Severity required a new desuperheater




## Capital Power



## New Desuperheater Installation

- New upgraded desuperheater purchased only the outer pipe spool, nozzles and manifold
- Major finding during first installation –
   DIFFUSER FAILURE
  - END PLATE LIBERATION
  - INTERNAL EROSION DAMAGE ON DIFFUSER
- Upgrade design modified to include new diffusers









## New Desuperheater w/ Diffuser

IMI Insyt

- Original "spool only" desuperheater sent back and modified to include new diffuser
- Final unit being installed this week!






## Hardware Upgrade






#### ORIGINAL DESUPERHEATER

#### UPGRADED DESUPERHEATER





- 1. New forged transition piece
- 2. Longer water legs
- 3. No water leg into water connection
- 4. Longer transition to diffuser
- 5. Liner removed

### Mitigation: Root Cause

Capital Power



- Your Problem
- Your Data
- Your System



imi insyt

- Solutions
- Savings
- Safety
- Value

- Our Knowledge
- Our History
- Our Tools



#### Be proactive

Identify plant and equipment issues before cracks and leaks occur.



#### Delve into data

Use data-driven analytics to improve plant safety and performance.



#### Improve your ROI

A system-wide analysis saves plant costs and avoids shutdowns.





### Data Set

- 4 weeks of data provided – 28 total starts across 3 units
- 104 discrete process variables across 3 units
- 10 second interval
- 25M data points loaded

UNIT 11 — 10 Starts				
17-MAY-21	COLD START 6:41AM	17-N		
17-MAY-21	Shutdown 20:12	17-N		
20-MAY-21	WARM START 1:50AM	20-N		
20-MAY-21	Shutdown 20:22	20-N		
21-MAY-21	HOT START 4:55AM	21-1		
21-MAY-21	Shutdown 15:22	21-N		
31-MAY-21	COLD START 5:12AM	31-N		
31-MAY-21	Shutdown 21:31	31-N		
01-JUN-21	HOT START 2:40AM			
01-JUN-21	Shutdown 23:36			
04-JUN-21	WARM START 3:49AM	04-J		
04-JUN-21	Shutdown 15:23	04-J		
06-JUN-21	WARM START 2:47AM	o6-J		
06-JUN-21	Shutdown 20:22	o6-J		
07-JUN-21	HOT START 4:22AM	07-J		
07-JUN-21	Shutdown 22:30	07-J		
08-JUN-21	HOT START 2:54AM	o8-J		
09-JUN-21	Shutdown 22:22	o9-J		
10-JUN-21	HOT START 5:01AM	10-J		
10-JUN-21	Shutdown 14:22	10-J		

UNI	UN				
17-MAY-21	COLD START 5:21AM	-			
17-MAY-21	Shutdown 20:12	-			
20-MAY-21	WARM START 1:22AM	20-MAY-21			
20-MAY-21	Shutdown 20:44	20-MAY-21			
21-MAY-21	HOT START 4:40AM	21-MAY-21			
21-MAY-21	Shutdown 15:47	21-MAY-21			
31-MAY-21	COLD START 4:55AM	31-MAY-21			
31-MAY-21	Shutdown 21:31	31-MAY-21			
-	-	01-JUN-21			
-	-	01-JUN-21			
04-JUN-21	COLD START 3:34AM	04-JUN-21			
04-JUN-21	Shutdown 15:42	04-JUN-21			
06-JUN-21	WARM START 2:21AM	06-JUN-21			
06-JUN-21	Shutdown 20:42	06-JUN-21			
07-JUN-21	HOT START 1:32AM	07-JUN-21			
07-JUN-21	Shutdown 22:46	07-JUN-21			
08-JUN-21	HOT START 2:42AM	08-JUN-21			
09-JUN-21	Shutdown 22:42	09-JUN-21			
10-JUN-21	HOT START 4:45AM	10-JUN-21			
10-JUN-21	Shutdown 14:43	10-JUN-21			

	UNIT 13 – 9 Starts		
	-	-	
	-	-	
	20-MAY-21	COLD START 1:22AM	
	20-MAY-21	Shutdown 20:43	
	21-MAY-21	HOT START 4:39AM	
	21-MAY-21	Shutdown 15:47	
	31-MAY-21	COLD START 4:53AM	
	31-MAY-21	Shutdown 18:21	
	01-JUN-21	HOT START 2:40AM	
	01-JUN-21	Shutdown 14:40	
	04-JUN-21	WARM START 3:28AM	
	04-JUN-21	Shutdown 15:42	
	06-JUN-21	WARM START 8:23AM	
	06-JUN-21	Shutdown 20:42	
	07-JUN-21	HOT START 1:38AM	
	07-JUN-21	Shutdown 22:46	
	08-JUN-21	HOT START 2:43AM	
	09-JUN-21	Shutdown 22:43	
	10-JUN-21	HOT START 4:45AM	
	an IIINI na	Chutdown	


Shutdown 14:43

### Where to Start?

- Capital Power
- Insyt

- Visualize the full data set? Excel UGH!
- What am I looking for? How deep do I go?














### Automation!




#### HRH Bypass Valve 1st Stage Desuperheater - Outlet Temperature Profiles



## Critical Finding #1



HRH Bypass Valve 1st Stage Desuperheater - Outlet Temperature Profiles




## Critical Finding #2






UNIT 11 - Outlet Temperature Profile - Steam Valve Closing After Startups




## Critical Finding #2














### Site Modifications

- Desuperheater hardware already upgraded
  - Final assembly being installed this week
- Third party process and controls specialist enlisted to modify control logic
  - IN PROCESS
    - Modify 5oC superheat override
    - Modify bypass lift point during startup
- Evaluating hardware upgrades for wetsteam erosion, EroSolve Trim





- Bypass valve cracking continues to plague Combined Cycle Plants
- Solution is multi-pronged
  - Hardware Upgrades
  - Data Review
  - Modify Operation
- Each system is Unique Thorough review required to completely mitigate failure
- If you haven't inspected recently...
  DO IT NOW!



