ACTUAL PLANT EXPERIENCE RESULTS OF AN ACOUSTIC MONITORING SYSTEM (AMS) FOR HRSG'S EARLY TUBE LEAK DETECTION



Presented at USA HRSG Forum on 09/24/2021.

By

(Tham) Thamarai P. Chelvan

Sr. Key Expert/ Fired Boiler, HRSG & BOPs/ O&M Technical Support Siemens Energy, Inc./4400 N. Alafaya Trail, Orlando, FL 32826, USA <u>Tham.Chelvan@siemens-energy.com</u> (407) 619-9700]

DISCLAIMER



The information, analyses, conclusions, recommendations and descriptions in this presentation: (i) are provided for information only, (ii) should not be considered as all inclusive or covering all contingencies, and (iii) ARE FURNISHED WITHOUT ANY WARRANTY WHATSOEVER, WHETHER EXPRESS OR IMPLIED, OF FITNESS FOR PURPOSE, MERCHANTABILITY, FROM COURSE OF DEALING OR USAGE OF TRADE, AS TO ADEQUACY, ACCURACY, COMPLETENESS OR USEFULNESS, OR OTHERWISE. Nothing in this presentation shall be deemed or construed to constitute a warranty or guarantee regarding, or any obligation, offer or commitment to provide any of the products or services referred to herein, nor as modifying or superseding any contractual requirements. Siemens assumes no liability for the use of or reliance for any purpose on this presentation, or any information, estimates, projections, results and/or data provided herein.

Unless otherwise specifically stated in this presentation, the observations, analyses, conclusions and recommendations in this presentation are based solely upon engineering evaluation and assessment of information and certain observations or inspections made by Siemens of the product(s) referenced. Any operational or plant historical information or data used or referred to herein was not independently verified by Siemens. Observations and assumptions made in this presentation may not reflect actual conditions.

Presented at **CRSG>FORUM**

TOPICS DISCUSSED



- 1. BACKGROUND INFORMATION ON WHY ACOUSTIC MONITORING SYSTEM (AMS) WAS INSTALLED
 - The Plant Information
 - The Plant's HP Economizer 2-1 Tube Leak Events
 - Root Cause Analysis Results for the Tube Leak Events and Recommended Modifications to Eliminate the Tube Leaks
 - Plant's Decision to Cost Effectively Manage the Tube Leak Events Through Early Detection of the Tube Leak
- 2. AMS DESCRIPTION & ITS INSTALLATION AT THE PLANT
- 3. AMS PERFORMANCE RESULTS
 - AMS detected every "Tube Leak Incidence" as soon as the Tube Leak Started



THE PLANT INFORMATION





- The Plant started commercial operation on December 15, 2009
- Siemens SCC5-4000F 2x1 (V94.3A) Gas Turbine with SST5-5000 Steam Turbine/ 50 Hz Frequency Generator
- Total Combined Electrical Output = 770 MW
- The Unit designed for firing natural gas at base load and limited No.2 oil firing, but ended up firing No.2 oil for 4 to 6 months period continuously
- Natural Circulation Drum Type Triple Pressure HRSGs, Units: 11 and 12

Tham Chelvan| O&M Tech Support

HRSG TUBE SECTIONS ARRANGEMENT

SIEMENS COCIGY



THE TUBE LEAK EVENTS & IMPORTANCE OF EARLY DETECTION OF TUBE LEAKS



- Boiler tube leak factor is one of the major causes of loss of generation in the Power Industry
- Undetected leaks can cause secondary damage and extend forced outages
- Small undetected leaks at inaccessible locations can go unrepaired during shutdowns, further grow in leak jet size and potentially cause further secondary damage to the adjacent tube rows and forced shutdowns
- At the subject plant, repeat tube leaks occurred in HP Economizer 2-1 tube Nos: 1-6, at right section of the top header from the water inlet feed pipe connection, indicated by the increase in the demineralized water usage
- At the subject plant, initial undetected leaks with continued plant operation created secondary damages to the adjacent tube rows, that lead to extensive tube repairs
- Acoustic Monitoring System (AMS) can help detecting the tube leaks as soon as they start occurring in the boiler systems



PLAY THE VIDEO OF A TYPICAL TUBE LEAK (VIEDIO SHOWS THE LEAK BY FAC AT CONDENSATE PREHEATER 2 LHS MODULE – OCCURRED DURING OCTOBER 2016 – SEE THE RED DOT)





Take Away Message From the Video is:

- High Sound Level of the Leak
- How the Leak Jet impinges to the adjacent tube row causing erosion & corrosion (see the discoloration at bottom 3 tubes due to wide spray angle water jet impingement during HRSG operation)

Presented at CRSG>FORUM

SIEMENS

UNIT 12 HRSG'S FIRST TUBE LEAK EVENT (FEB. 4, 2013) INDICATED BY HIGH MAKE-UP WATER USE AT HP ECON 2-1 AFTER ABOUT 3 YEARS FROM COMMERCIAL OPERATION & ITS IMMEDIATE SHUT DOWN & REPAIR



2021-09-24

Tham Chelvan |O&M Tech Support 8 Unrestricted © Siemens Energy, 2021

Presented at **CHRSG** FORUM

SIEMENS COCIGY UNIT 12 HRSG'S ADDITIONAL TUBE LEAKS DUE TO FEW MONTHS OF CONTINUED OPERATION WITH LEAK (FOUND ON 6/10/2013) -PRIMARY TUBE LEAK CRACKS & SECONDARY WATER JET EROSION & CORROSION DAMAGE TO ADJACENT ROW TUBES





1. Full Circumference Cracked Tube No. 3 (Red) & 2. Partially Cracked Tube No.5 (Red) at Tube Joint on Header 29 as Primary Source of Water Jet Leak



3. Hole on VIP2 tube (Red) Due to HP2-1 Tube Leak Water Jet Erosion



SIEMENS

energy

4. Erosion & Corrosion Damage on VIP2 Tubes (Blue) Due to HP2-1 Tube Water Jet Leak

Tham Chelvan| O&M Tech Support 9

Unrestricted © Siemens Energy, 2021

UNIT 11 HRSG'S PRIMARY & SECONDARY TUBE LEAKS FOUND ON JULY 19, 2013, AFTER FINDING PRIMARY & SECONDARY TUBE DAMAGES IN UNIT 12.





Primary Leak Source - Crack Facing Header 27 at Front Row Tube No. 5 Joint of Header 29 – See Water Jet Leak Area Marks

Presented at **CRSG>FORUM**

Tham Chelvan| O&M Tech Support 10

Unrestricted © Siemens Energy, 2021

SIEMENS

UNIT 11 HRSG'S PRIMARY & SECONDARY TUBE LEAKS SIEMENS FOUND ON JULY 19, 2013 & REPAIRS PERFORMED PHOTOS



Tube No: 5 & 6 on Header 27 with Holes & Low Thickness Due to Erosion & Corrosion

Tube No: 7 on Header 27 with a Crack & Tube Plug with Header Window Cutting Method

Erosion & Corrosion Damage (Blue) on Header 27 Due to HP2-1 Tube No: 5 Water Jet Leak



PRIMARY & SECONDARY TUBE DAMAGES RESULTED IN EXPENSIVE& EXTENSIVE MULTIPLE ROWS OF TUBE CUTTING FOR ACCESS ANDREPAIR WELDING WITH NEW REPLACEMENT PLAIN TUBE SECTIONS(SPENT >\$1.5 MILLION US\$ FOR TWO MODULES REPAIR, ONE IN EACH UNIT)





Presented at **CHRSG** FORUM

SIEMENS

²⁰²¹⁻⁰⁹⁻²⁴ Siemens Energy is a trademark licensed by Siemens AG.

ROOT CAUSE FOR THE HP ECONOMIZER 2-1 REPEAT TUBE LEAK EVENTS & RECOMMENDED MODIFICATIONS TO ELIMINATE THE HP 2-1 TUBE LEAKS

Siemens Energy, Inc. (SEI) Measured Extensive Tube Metal Temperatures & Performed 3D Plexiglass Physical & CFD Flow Modeling Studies. Based on these Studies, the Primary Root Cause Result: "Reverse Flow" in downward water flow pass from insufficient pressure head to overcome the "Upward Buoyancy Forces" created by "Water Density Differences". Recommended Modifications to Eliminate HP Econ 2-1 Tube Leaks: Modify "Feed Pipes" for upward flow in all 4 passes of the same row header.

Measured Temperature Data Calibrated CFD Model's Predicted Temperature Distribution in Existing Arrangement: In tubes with reverse flow is ~540°F to 590°F near inlet header; Water Outlet Temperature: 480°F



INTRODUCTION TO ACOUSTIC MONITORING SYSTEM SIEMENS **TO DETECT TUBE LEAKS & ITS GENERIC** <u>e</u>nergy DIFFERENTIATING FEATURES FROM TRADITIONAL METHODS

- Traditional methods of tube leak detection are: •
 - Sudden or slow increase in the demineralized makeup water usage 1.
 - High moisture content in HRSG exit flue gas 2.
 - 3. Steam in the stack plume
 - 4. Wet spots at the bottom of the HRSG
- Traditional methods do not typically locate the specific area of tube failure •
- Latest technology is the use of Acoustic Monitoring System (AMS) •
- The AMS detects leaks earlier than traditional methods, and it is an on-line real time tube • leak detection (24-7 real time monitoring, with local and network alarming)
- It provides an early primary tube leak detection, and the immediate repair of primary • leak-tube-crack reduces secondary tube damages
- It locates area of leak(s) before unit comes offline, and it trends the severity and • progression of the leak with real time data
- Depending on the severity of tube leak, it helps managing market exposure and risk, and • allows planning the tube leak repair during planned outage or period of low MW demand
- It has Non-intrusive sensors & After-market install •
- It can be installed to provide total HRSG tubes area coverage or in areas of most concern •

INSTALLED EQUIPMENT AT THE SUBJECT PLANT TO HELP MANAGE THE TUBE LEAK EVENTS BETTER



- The estimated capital budget needed for the subject plant's HRSG HP Econ 2-1 recommended feed & exit pipes modification to eliminate HP Econ 2-1 repeat tube leak events was significant (about US\$3.5 million for the two HRSGs)
- The plant looked for ideas to manage the tube leak problem better and minimize the repair costs
- SEI recommended the AMS System which is intended to help with an early detection of primary tube leak, to minimize secondary water jet impingement damages, and to minimize expensive repair cost of both the primary leak and secondary leak damaged tubes
- The reason for recommending Mistras/Triple 5 AMS was the following Installations & Monitoring Experience they had:
 - o 21 HRSG's
 - 375+ Power Boilers
 - 500+ Feedwater Heaters
 - o 21 Recovery Boilers

o 100+ Boilers in Surveillance Program

Presented at CRSG~FORUM

- o 170+ Sites
- o 65+ Companies
- o 9900+ Total sensors
- 2500+ leaks cataloged in Triple 5's database since 2004
- The plant decided to implement the AMS System to detect the primary tube leaks early
- Mistras/Triple 5 provided the AMS
- Even though the AMS installation started during April 2016, after the plant had a tube leak repair incidence at HP Econ 2-1 bottom header 30 on June 12, 2016 (a forced outage), it escalated the importance of completing the installation and it was completed during July 2016.

MISTRAS/TRIPLE 5 - ACOUSTIC MONITORING SYSTEM (AMS) FOR SUBJECT PLANT

SIEMENS energy

Factors Affecting Waveguide Locations

- Sensitivity of • the sensor is 20 to 30 feet radius
- Coverage in • areas of the boilers where leaks most expected
- Accessibility at each desired location
- 19,20 15,16 11.12 7,8 3.4 HRSG 11 & 12 20 Sensor Locations Each — indicates 2 sensors on Top Each — indicates 2 sensors on sidewalls Even # on Right Side Odd # on Left Side - The second second 100.685 5,6 9,10 1,2 13,14 17,18 a) 368 RANGE T 14.43 O SHARE CHT HAND ELEVATION 60 NEW COLORAD PROPERTY OF GAS FLOW Tham Chelvan| O&M Tech Support 16 Presented at CRSG>FORUM Siemens Energy is a trademark licensed by Siemens AG. Unrestricted © Siemens Energy, 2021
- **Economics**

SUBJECT PLANT'S HRSG SENSORS LOCATION ID DISPLAY MAP

SIEMENS COCIGY

- ACOUSTIC MONITORING SYSTEM [SENSOR MAP] X AMS DISPLAYS BOILER SELECTION - 8 × ******** ***** Unit # 11. HRSG 11 SENSOR: FL: DESCRIPTION: 1A/1B 6 SH 3-4 / RHT 3 - Top Right 2A/2B 1 SH 3-4 / RHT 3 - Bottom Left 3A/3B SH 3-4 / RHT 3 - Top Left 6 4A/4B SH 1-2 / RHT 1-2 - Bottom Left 1 5A/5B 6 SH 1-2 / RHT 1-2 - Top Right 6A/6B 6 SH 1-2 / RHT 1-2 - Top Left 7A/7B 6 VHP 1-3 / EHP 3 - Top Right 8A/8B 6 VHP 1-3 / EHP 3 - Top Left 9A/9B 6 EHP 2 / VIP 1-2 - Top Right 10A/10B 6 EHP 2 / VIP 1-2 - Top Left 11A/11B 6 HP1 / LP 1-2 - Top Right 6 12A/12B HP1 / LP 1-2- Top Left 13A/13B 1 VHP 1-3 / EHP 3 - Bottom Left 184 174 16A 178 168 14A/14B EHP 2 / VIP 1-2 - Bottom Left 1 15A/15B 1 HP1 / LP 1-2 - Bottom Left 16A/16B 1 HP1 / LP 1-2 - Bottom Right 17A/17B 1 EHP 2 / VIP 1-2 - Bottom Right 18A/18B VHP 1-3 / EHP 3 - Bottom Right 1 19A/19B 1 SH 1-2 / RHT 1-2 - Bottom Right NOSB 20A/20B 1 SH 3-4 / RHT 3 - Bottom Right "A" channels monitor frequency band 1.0 kHz to 4.0 kHz The full allowable bandwidth is 0.2 kHz to 10.0 kHz "B" channels monitor frequency band 25.0 kHz to 175 kHz TNDS 12:41:04 01/17/2017 ٠ MABE BAR MAP BLR -15 PLANT TND SPEC JRN STAT -Tham Chelvan| O&M Tech Support 17
- Color Coded For Signal Strength
- Customized To Subject Plant's Nomenclature

2021-09-24 Siemens Energy is a trademark licensed by Siemens AG.

Presented at

Unrestricted © Siemens Energy, 2021

HOW ACOUSTIC MONITORING WORKS



- AMS involves continuous measurement of sounds from within the HRSG
- Tube leaks create noise that travels through the boiler gasses
- Leak noise travels until it "hits" the inner liner
- Leak noise also travels through fused metal pathways, such as the inner liner
- This noise causes the inner liner, sounding rod and sensor to vibrate
- Sensor converts vibration to electrical energy that is trended and alarmed in the monitoring system



Unrestricted © Siemens Energy, 2021

ACOUSTIC MONITORING SYSTEM COMPONENTS SIEMENS



HRSG ACOUSTIC MONITORING SYSTEM INSTALLED COMPONENTS

SIEMENS energy

SM-2 Sounding Rod

- Noninvasive rods welded to • inner liner
- Sensor mounted on end .
- Covered with sensor box for • protection

Amplifier Box

2021-09-24

- · Accepts input from 2 sensors
- Daisy chained to minimize cable runs
- AFB's can be contained in large NEMA's located on top and bottom elevations





Remote Power Box Accepts 120 / 240 VA Powers the field with

Attachment

Cabinet Enclosure

Plant



Desktop Enclosure



Tham Chelvan| O&M Tech Support 20 Unrestricted © Siemens Energy, 2021

Siemens Energy is a trademark licensed by Siemens AG.

Presented at **CHRSG** FORUM

ACOUSTIC MONITORING SYSTEM – RELATIVE DISTANCE BETWEEN COMPONENTS







EXAMPLE NORMAL BACKGROUND NOISE OF AMS





Siemens Energy is a trademark licensed by Siemens AG.

Presented at **HRSG** FORUM

Unrestricted © Siemens Energy, 2021

1ST TUBE LEAK DETECTION BY AMS AFTER 2 MONTHS OF ITS INSTALLATION AT SUBJECT PLANT (9/12/2016 HP ECON 2-1 TUBE NO. 5 FRONT ROW ON TOP HEADER 29 – LEAKED FOR 57 HOURS ABOVE ALARM LEVEL)



Tham Chelvan| O&M Tech Support 23

Unrestricted © Siemens Energy, 2021

SIEMENS

energy

Siemens Energy is a trademark licensed by Siemens AG. Pr

2021-09-24

Presented at

FREQUENCY DISTRIBUTION OF THE ENERGY FOR BEFORE & AFTER THE LEAK EVENT SIGNALS (9/12/2016 HP ECON 2-1 TUBE NO: 5 LEAK **REPAIR EVENT) - TRENDS SEVERITY AND PROGRESSION OF LEAK**





Unrestricted © Siemens Energy, 2021

FREQUENCY DISTRIBUTION OF THE ENERGY FOR FULLY **SIEMENS DEVELOPED LEAK SIGNALS ON DIFFERENT DAYS** energy (9/12/2016 HP ECON 2-1 TUBE LEAK REPAIR EVENT)



Unrestricted © Siemens Energy, 2021

FREQUENCY DISTRIBUTION OF THE ENERGY FOR AFTER THE LEAK SIGNALS (9/12/2016 HP ECON 2-1 ACTIVE TUBE LEAK LOCATION PHOTO)







9/12/2016 – Found Leak Jets at HP Econ 2-1 Tube No. 5 Front Row of Top Header 29 - LHS Module - Channel 10 B Are







Tham Chelvan | O&M Tech Support 26 Unrestricted © Siemens Energy, 2021



1ST TUBE LEAK DETECTION BY AMS AFTER 2 MONTHS OF ITS INSTALLATION AT SUBJECT PLANT (9/12/2016 HP ECON 2-1 TUBE NO. 5 FRONT ROW ON TOP HEADER 29 LOCATION & PHOTO OF NARROW AVAILABLE PENTHOUSE AREA SPACE FOR WELDING ACCESS)



9/12/2016 HP ECON 2-1 TUBE NO. 5 TOP HEADER AFTER REPAIR WELDING PHOTOS & AFTER REPAIR SIGNALS TREND





2021-09-24



After Repair Signals Went Back To Normal Level



Tham Chelvan| O&M Tech Support 28

Unrestricted © Siemens Energy, 2021

Siemens Energy is a trademark licensed by Siemens AG.

2ND TUBE LEAK DETECTION BY AMS (01/15/2017 HP ECON 2-1 TUBE NO: 5 FRONT ROW AT BOTTOM HEADER 30 LHS COCIGY MODULE - LEAK SIGNAL TREND)



2021-09-24

Tham Chelvan| O&M Tech Support 29

Presented at **drsg** Forum



2ND TUBE LEAK DETECTION BY AMS (01/15/2017 HP ECON 2-1 TUBE NO: 5 FRONT ROW AT BOTTOM HEADER 30 LHS COCIGY MODULE - LEAK LOCATION & REPAIR PHOTO)





Siemens Energy is a trademark licensed by Siemens AG.

Presented at **CRSG>FORUM**



3RD TUBE LEAK DETECTION BY AMS (10/19/2017 HP ECON 2-1 TUBE NO. 4 & 5 FRONT ROW ON TOP HEADER 29 SIEMENS LOCATION – LEAK SIGNAL TREND)

Recoustic monitoring system - [signal trend]

AMS DISPLAYS BOILER SELECTION THERMOCOUPLE PULVERIZER



Tham Chelvan| O&M Tech Support 31

Presented at

3RD TUBE LEAK DETECTION BY AMS (10/19/2017 HP ECON 2-1 TUBE NO. 4 FRONT ROW ON HEADER 29 LHS MODULE- SIEMENS **TUBE LEAK LOCATION & REPAIR PHOTOS)**



Unrestricted © Siemens Energy, 2021

Siemens Energy is a trademark licensed by Siemens AG.

3RD TUBE LEAK DETECTION BY AMS (10/19/2017 HP ECON 2-1 TUBE NO. 5 **SIEMENS** FRONT ROW ON HEADER 29 LHS MODULE – TUBE LEAK LOCATION & COCOS REPAIR PHOTOS – CRACK AT THE SAME WELD OF THE 1ST TUBE LEAK REPAIR)



2021-09-24

Siemens Energy is a trademark licensed by Siemens AG.



Tham Chelvan | O&M Tech Support 33 Unrestricted © Siemens Energy, 2021

4TH TUBE LEAK DETECTION BY AMS (03/10/2018 HP ECON 2-1 TUBE NO: 6 FRONT ROW ON HEADER 29 LHS MODULE – LEAK SIGNAL TRENDS)





Presented at **CHRSG** FORUM

Unrestricted © Siemens Energy, 2021

SIEMENS

4TH TUBE LEAK DETECTION BY AMS (03/10/2018 HP ECON 2-1 TUBE NO: 6 FRONT ROW ON HEADER 29 LHS MODULE SIEMENS – LEAK LOCATION & REPAIR PHOTOS)



2021-09-24

Siemens Energy is a trademark licensed by Siemens AG.

Presented at **HRSG** FORUM

5TH TUBE LEAK DETECTION BY AMS (11/05/2018 IP EVAPORATOR PIN HOLE TUBE LEAK – SIGNAL TRENDS)



SIEMENS



5TH TUBE LEAK DETECTION BY AMS (11/05/2018 IP EVAPORATOR PIN HOLE TUBE LEAK – LEAK LOCATION & SIEMENS AFTER REPAIR PHOTOS)



2021-09-24

Presented at **CHRSG** FORUM

Unrestricted © Siemens Energy, 2021

6TH & 7TH TUBE LEAK DETECTION BY AMS (6TH IS FOR HP ECON 2-1 TUBE NO: 5 BOTTOM HEADER NO: 30 & TUBE NO: 37 AT TOP HEADER 29 FRONT ROW TUBES & 7TH IS FOR TUBE NO: 5 & 6 FRONT ROW OF TOP HEADER 29 LHS MODULE – LEAK SIGNAL TRENDS)



SIEMENS COCIGY

6TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 5 BOTTOM HEADER NO: 30 & TUBE NO: 37 AT TOP HEADER 29 FRONT ROW TUBES – SIEMENS LHS MODULE (01/06/2020) – LEAK LOCATION & REPAIR PHOTOS)



2021-09-24

Siemens Energy is a trademark licensed by Siemens AG.

Presented at **HRSG~FORUM**

Unrestricted © Siemens Energy, 2021

7TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 5 & 6 FRONT **SIEMENS** ROW OF TOP HEADER 29 LHS MODULE (02/08/2020) – LEAK JET LOCATION & REPAIR PHOTOS – SAME TUBES OF 3RD & 4TH INCIDENCE WELD REPAIRS



8TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 5 FRONT ROW OF BOTTOM HEADER 30 HAD REPEAT CRACK LEAK ON 02/20/2020 - SIEMENS SAME LOCATION AS THE 2ND INCIDENCE) – LEAK SIGNAL TRENDS)



8TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 5 FRONT **SIEMENS** ROW OF BOTTOM HEADER 30 HAD REPEAT CRACK LEAK ON 02/20/2020 - COCY SAME LOCATION AS THE 2ND INCIDENCE) – LEAK LOCATION & REPAIR PHOTO)



Tham Chelvan | O&M Tech Support 42 Unrestricted © Siemens Energy, 2021

9TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 4 REAR ROW OF TOP HEADER 29 LHS MODULE (10/08/2020) – LEAK SIGNAL TRENDS)



Tham Chelvan| O&M Tech Support 43

²⁰²¹⁻⁰⁹⁻²⁴ Siemens Energy is a trademark licensed by Siemens AG.

Presented at

Unrestricted © Siemens Energy, 2021

SIEMENS

9TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 4 REAR ROW OF TOP HEADER 29 LHS MODULE (10/08/2020) – LEAK SIGNAL TRENDS)



Presented at **HRSG** FORUM

Unrestricted © Siemens Energy, 2021

SIEMENS

9TH TUBE LEAK DETECTION BY AMS (HP ECON 2-1 TUBE NO: 4 REAR ROW OF TOP HEADER 29 LHS MODULE (10/08/2020) – LEAK LOCATION & REPAIR PHOTOS)



2021-09-24

Siemens Energy is a trademark licensed by Siemens AG.

Presented at CRSG~FORUM

Unrestricted © Siemens Energy, 2021

SIEMENS

1ST TUBE LEAK DETECTION BY AMS IN UNIT 12 (IP EVAPORATOR 1 TUBE NO:15 FROM RHS OF BOTTOM RHS MODULE HEADER 34 (08/15/2017) – LEAK SIGNAL TRENDS) C∩CΓGY



1ST TUBE LEAK DETECTION BY AMS IN UNIT 12 (IP EVAPORATOR 1 TUBE NO:15 FROM RHS OF BOTTOM RHS MODULE HEADER 34 (08/15/2017)- LEAK & REPAIR PHOTOS)



1ST TUBE LEAK DETECTION BY AMS IN UNIT 12 (IP EVAPORATOR 1 TUBE NO:15 FROM RHS OF BOTTOM RHS MODULE HEADER 34 (08/15/2017)– PIN HOLE & REPAIR PHOTOS)



²⁰²¹⁻⁰⁹⁻²⁴ Siemens Energy is a trademark licensed by Siemens AG.



Presented at **CRUM**

SUMMARY



- The subject plant's HRSG HP Econ 2-1 Circuit had a "Reverse Flow" in downward water flow pass from insufficient pressure head to overcome the "Upward Buoyancy Forces" created by "Water Density Differences"
- The above factor resulted in multiple repeat tube leaks at Header 29 RHS end tubes 1 through 6
- To eliminate the repeat tube cracks, SEI recommended to modify the "Feed Pipes & Exit Pipes" for upward flow in all 4 passes of the same row headers: 29 (top header) & 30 (bottom header)
- The plant decided that the feed and exit pipe modification was expensive and decided to manage the repeat tube leak incidences with immediate tube repairs
- For early detection of tube leaks and immediate tube repair, SEI recommended to install AMS system & the subject plant installed it in both HRSG units 11 & 12
- The installed AMS system description and performance results were presented
- The installed AMS system was successfully detecting all the tube leak incidences as soon as the tube leak starts occurring, well before any of the traditional method's indication, and quick tube repairs were performed immediately before they cause secondary damages, and managed effectively
- Unit 11 had a greater number of tube leak events than Unit 12
- The subject plant was very happy on the performance of the installed AMS system

Tham Chelvan| O&M Tech Support 49

Presented at **CHRSG** FORUM

