


HP Bypass Valve Erosion Panel Discussion




POLLING QUESTION (See side panel):
Has your plant experienced bypass valve erosion?


HP Bypass PCV Erosion

- Caused by water and/or wet steam passing through valve
- Not specific to any PCV OEM







PLANT A – BYPASS OPENS WELL AFTER LIGHTOFF




PLANT A – BYPASS OPENS WELL AFTER LIGHTOFF




PLANT A – BYPASS OPENS WELL AFTER LIGHTOFF



PLANT B – BYPASS OPENS @ LIGHTOFF



PLANT B – BYPASS OPENS @ LIGHTOFF



PLANT B – BYPASS OPENS @ LIGHTOFF

